











SR 1/Thompsonville Interchange Kent County, Delaware

-  DelDot Survey Monument
-  Wetland Flag Point
-  Wetland Boundary
-  Wetland Continues
-  "Waters of U.S." Continues
-  "Waters of U.S."
-  Study Area Boundary
-  Tax Parcel

Note: There are non-federally regulated waters of the U.S. (i.e. swales/ditches) along all the roadways within the study area. The sections of these roadside ditches which are federally regulated are indicated on the plans. The non-federally regulated waters of the U.S. sections are comprised of swales with no obvious indications of a high water mark.

Sources:
1999 Aerial Photography
Century Engineering
Kent County, Delaware
A.D. Marble Site Investigation

Wetland Overview

500 0 500
Feet

April 8, 2004